

09/10/90

RECORD NUMBER: 161

MINE IDENTIFICATION NUMBER

M045017

MINE NAME: MERCUR MINE

OPERATOR: BARRICK MERCUR GOLD MINES, INC

SURFACE OWNER:PRIVATE

LEASE #:

MINERAL OWNER:PRIVATE

TOWNSHIP : 6.0S

RANGE: 3.0W

SEC: 4

QTR:

QTR/QTR:

PERMIT STATUS: APP

MINE TYPE [(S)urface, (U)nderground]: S

MINE STATUS (PRO,ACT,SUS,RET): ACT

ACREAGE: 1719

MINERALS MINED

40

41

0

DATE  
RECEIVED

TENTATIVE APPROVAL  
DATE

FINAL APPROVAL  
DATE

03/10/81

05/01/81

10/13/81

BOND TYPE:SELF

BOND AMOUNT:8808891

ANNUAL REPORT YEAR:89

COMMENTS:

Inpsection made to discuss ongoing dump leach #3 construction. Also to evaluate cyanide solution spill of 40-60 lbs sodium cyanide. Structures not adequate to handle such a spill of this magnitude. JBR working w/operator to see if a clay cap needs to be installed over dump leach #3.